



EZ- C O D r[®]
Quick User Guide
rev. 1.21



EZ-FIBr®

SIGN IN

Where the world builds connectivity

Hundreds of telecom operators and Information Technology companies, Configure, Tune, Diagnose and maintain their Optical Fibre Networks

The World most advanced optical connectivity platform !

SIGN UP



EZ-FIBr 2021 ©

Sign In the
EZ-FIBr®
Web Page !




EZ-FIBr®

Pro Tools EZ-FIBr OTC M

EZ-CHECKr®

- EZ-CHECKr®
- EZ-CODr®
- EZ-DOCTr®
- EZ-TUNr®

PN: SPDTU080100D-ADV
SN: ZAB2F10002
REV: A
Comp. with: CISCO-Skylane
Tunable
Channel: C19



EZ-FIBr © 2021 EZ-MWr v. 0.00.062 [COOKIE SETTINGS](#)

Open the
EZ-FIBr®
ToolBox !



EZ-FIBr®

Pro Tools EZ-FIBr OTC M

EZ-CHECKr®

- EZ-CHECKr®
- EZ-CODr®
- EZ-DOCTr®
- EZ-TUNr®

Let you update the optical transceiver configuration settings!

TU080100D-ADV


2AB2F10002

REV: A

Comp. with:
CISCO-Skylane

Tunable

Channel: C19



EZ-FIBr © 2021

EZ-MWr v. 0.00.062

[COOKIES SETTINGS](#)

Select the
EZ-FIBr®
Tool !



The screenshot shows the EZ-FIBr software interface. At the top left is the EZ-FIBr logo. At the top right, there are buttons for "Pro Tools" and "EZ-FIBr OTC", and a user profile icon labeled "M". Below the header, there is a dropdown menu showing "EZ-CODr". The main content area is dimmed, showing a technical drawing of a device with the following specifications:

- PN: SPDTU080100D-ADV
- SN: 2ABZF10002
- REV: A
- Comp. with: CISCO-Skylane

A modal warning box is centered on the screen with the following text:

EZ-CODr® Warning!!!

Don't unplug the EZ-FIBr OTC nor the optical transceiver until the EZ-CODr® process is complete!

Dont show me again

CONTINUE

At the bottom of the interface, there is a footer with "EZ-FIBr © 2021", "EZ-MWr v. 0.00.062", and a link for "COOKIES SETTINGS".

Read the
EZ-CODr®
Warning message!




EZ-FIBr® Pro Tools EZ-FIBr OTC M

EZ-CODr® EZ-FIBr® Search

Cisco DWDM-SFP10G-C-S A	frequently used
Nokia - Alcatel 3HE05833CA A	frequently used
Optelion 1025-3700 A	frequently used
Adva	frequently used

CANCEL CODE



EZ-FIBr © 2021 EZ-MWr v. 0.00.062 COOKIES SETTINGS

Once on the EZ-COD r® page

Follow the
easy as
1, 2, 3
coding process




EZ-FIBr® Pro Tools EZ-FIBr OTC M

EZ-CODr® EZ-FIBr® Search

LSRU DWDM-SFP10G-C-S A	frequently used
Nokia - Alcatel 3HE05833CA A	frequently used
Optelion 1025-3700 A	frequently used
Adva SFP/11GU/DCTV/SM/LC#TUN A	frequently used

CANCEL CODE



EZ-FIBr © 2021 EZ-MWr v. 0.00.062 COOKIES SETTINGS

1

SELECT
the desired configuration !



EZ-FIBr®

Pro Tools EZ-FIBr OTC M


EZ-CODr® EZ-FIBr® Search

CISCO DWDM-SFP10G-C-S A	frequently used
Nokia - Alcatel 3HE05833CA A	frequently used
Optelion 1025-3700 A	frequently used
Adva SFP/11GU/DCTV/SM/LC#TUN A	frequently used

CONFIRM

Are you sure you want to update your optical transceiver as Adva from EZ-FIBr® coding server ?

CANCEL CONFIRM



EZ-FIBr © 2021 EZ-MWr v. 0.00.062 COOKIES SETTINGS

2

CONFIRM
your selection !



Pro Tools EZ-FIBr OTC M

EZ-CODr® EZ-FIBr® Search

Click DWDM-SFP10G-C-S | A frequently used

Nokia - Alcatel 3HE05833CA | A frequently used

Optelion 1025-3700 | A frequently used


Advant SFP/11GU/DCTV/SM/LC#TUN | A frequently used

CODING WITH : ADVA

Don't unplug the accessory nor the optical transceiver until the process is complete !

ABORT CODING


CANCEL CODE



15%

EZ-FIBr © 2021 EZ-MWr v. 0.00.062 COORDS SETTINGS


Set Up in Progress!





EZ-CHECKr®

PN: SPDTU080100D-F70
SN: 2AB2F10002
REV: A
Comp. with:
ADVA
Tunable
Channel: C19



3

it's **CODED !**



EZ- COD r[®]

Tips & Tricks

rev. 1.21



- select the preferred CODING service provider.
- use the search engine to filter the list choice.
- customize the COMPATIBILITY list.

Did you know ?

- last used coding selection values are highlighted for optimized efficiency.
- customize your tuning grid